Vehicle/Situation Specific Examples

MAZDA	
Assertion	Brand Response
Mazda 6 Diesel	Each repair could have been completed through any independent repairer purchasing a Mazda Modular Diagnostic System (M-MDS). This would permit unhindered access to resolve both repairs, minimising the unnecessary delay of the repairers having to take it to a Dealership and then requesting that additional time for the Dealership staff to safely drive the vehicle into the workshop, connect the vehicle and complete the module setup, then return it to the repairer.
Must be connected the factory computer via internet and have software updates for the ECM. Must be completed by the	The two examples cited have not previously been raised to the awareness of Mazda Australia and do not match with any known request for independent repairer information through the publicly available
	FCAI weblink (http://www.fcai.com.au/service-repair/member-service-repair). This link confirms that repairers need simply email customersupport@mazda.com.au to make a request for information. This is the first time that we have become aware of any of the formal AAAA reporting instances.
 consumer requested access to the update to be provided to their repairer – access denied 	As of 2 nd November 2016, this link was further upgraded to a dedicated Australian-developed portal for access to Mazda's Workshop manuals identical to that offered online to Dealerships. This portal includes full Body Repair information, Wiring Diagrams, Workshop Manuals and Technical information at www.mazdamanuals.com.au for a time-based subscription.
	Both examples would simply require an independent repairer to purchase a diagnostic tool that is required of all authorised Mazda Dealerships. This diagnostic tool is publicly available to purchase through Mazda Australia and there are no restrictions or price difference placed upon purchase to any party. There have been no enquiries to purchase a Mazda diagnostic tool since the commencement of the FCAI Code of Conduct.
Mazda 3 2005	
Power steering module failure, needs to be connected to the factory tool via the internet to	Regarding the "arbitrary fee" mentioned, this is not something that is set or prescribed by Mazda Australia under any direction to Dealers. The nominal time mentioned in the submission is something
get the new module initialised. Repairer	that any business should reasonably and fairly be able to recover as a result time and staff support
installed power steering module according to manufacturer's specifications – final step	provided – which is exactly what appears to have been done in this instance.

	vehicle returned to the customer.
	amount because the repairer wanted to get the
-	an unnecessary fee which was set at an arbitrary
	required dealership involvement and payment of

It would be against the spirit of fair and reasonable access to information for any repairer to rely upon another repairer (Dealer or otherwise) to not provide nominal and fair recovery of time and technology invested in support of providing the information

MIISUBISHI	
Assertion	Brand Response
Mitsubishi Triton Diesel	
Has had issues where dealer internet updates	From the 08MY Triton onwards:
direct to the car are the only fix (diesel injectors	 Learned values for the injectors can be saved by aftermarket scan tools or manually written
learned values, poor performance).	down. If the information needs to be re entered, this can once again be done with the
	appropriate aftermarket scan tool.
	 If injectors are to be replaced then the code is printed on the injector and can be manually
	entered.
	 Selected after-market scan tools also have the ability to perform the SQIL (small quantity
	injection learn) which helps for any deficiency in injector condition or engine condition. This
	 Regarding diagnostics around leant injector values (SQIL) and poor "performance", information
	is contained within the workshop manual and may relate to Diagnostic Trouble Code (DTC)
	procedure or symptom procedure. The workshop manual in CD form can be purchased from
	the Mitsubishi Dealer Network.
	Mitsubishi Motors believes that it complies with the requirements of the voluntary code providing
	service and repair information.
Mitsubishi Rosa	
Bus-passenger door actuator, (wiring diagram) unable to source wiring information, Warranty	The Mitsubishi Rosa is a bus and not a light vehicle and so is not covered by this Agreement.

Assertion	JEEP
Brand Response	

Jeep XJ Cherokee	
Unable to get information, wiring diagrams	Fiat Chrysler Automobiles (FCA) has a technical information website that independent repairers can
not running – no fault codes. Car had to be	information is available for a subscription fee that can be purchased for as little as one day in case
returned to the dealer to have it diagnosed. (A	repairers see few vehicles in their workshop.
faulty injector) which could also only be	
programed via the dealer.	
Jeep Grand Cherokee	
I recently purchased a tool that will allow me to	These codes are used to program keys and modules to vehicles and therefore represent a serious
program many different vehicles (CarDAQ-M).	security risk. We would expect that the owner of the vehicle request this "pin" from our dealerships so
I had a Jeep Grand Cherokee in the shop last	the necessary checks could be performed before this type of information is given. With the vehicle in an
month. It had a fault and the check engine light	independent workshop we have no way of determining that the person requesting the pin has the
was on and fault codes for oxygen sensors.	owner's permission.
I went to the Chrysler website and purchased a	
the VIN number and was excited to find that the	
VIN was recognised. That means that this exact	
vehicle was supported and I was able to search	
for technical service bulletins, look at service	
information, wiring diagrams, etc.	
I found a TSB that addressed the exact problem	
that this vehicle had. Chrysler had released a	
new software update (calibration file) to resolve	
this exact problem with the oxygen sensors.	
Great Stuff! With my one day subscription I can	
download the necessary software that will	
interfaces the CarDAQ with the vehicles	
computer. I search and find the calibration file	
and see a warning notice on the webpage. The	
notice warns that once the update is performed	
that the immobiliser (SKIM) will need to be	
reprogrammed and a PIN code will be required.	

providing customers with alternatives to the services offered to customers by authorised Dealers. Independent repairers are able to have access to most of Jaguar Land Rover's technical information, as available to authorised Dealers, with the exception of security serial numbers and key codes. Jaguar Land Rover does, however, consider that there are clear quality advantages for customers who choose to have their Jaguar and Land Rover vehicles services at authorised service centres. This is	
Jaguar Land Rover recognises and readily acknowledges the role that independent repairers play in	JAGUAR
	have the customer return to the dealer.
	were unable to fix the problem and needed to
	around and they can't help. So once again, we
	we followed up but were told that guy isn't
	and we have never received the information so
	time, we provided our fax number and contact
	told they don't allow this but they would this
	information, so we tried another dealer and was
repairers see few vehicles in their workshop.	the first person told us they can't provide that
information is available for a subscription fee that can be purchased for as little as one day incase	we requested the electronic diagram from jeep
reference to find and use wiring diagrams, rebuild procedures, diagnostic test and so on. This	had a intermitted issue with the head light and
Fiat Chrysler Automobiles (FCA) has a technical information website that independent repairers can	A customer came into Umina with a Jeep and
	Jeep
	any further because I couldn't get the code.
	and I had the calibration file. But I couldn't go
	tool, I had the subscription, I had the software
	Very frustrating, I was so close. I had the scan
	the code but that didn't help. No joy.
	had the scan tool and I was willing to purchase
	tool to do the programming' I explained that I
	information and besides you need a special scan
	typical response 'we cannot give you that
	Chrysler dealership service manager and get the
	So I get on the phone and speak to the nearest
	On, great

 Screen To com availab In the program vehicle 	•	order the computer, however, we had to return the vehicle to the dealer to have the computer re programed with the vehicles specifications so an ap		front, two middle & one rear. We found information and could communicate and read • The b	Assertion Brand Response	The resources whenever a Jaguar Land R	into training, high custome Rover service
Screen shots from both websites are attached. To complete the proposed repair will require software for the diagnostic unit and this is available by subscription to the online library via a link on the TOPIx website. In the particular repair issue raised, provided the repairer followed the processes above, it would not have been necessary to take the vehicle back to a Jaguar Dealer, as the module programming would be completed from data within the tool and security information from the vehicle.		 Browsing TOPIx without registering Some vehicle components, when replaced may require programming and thus the use of an appropriate diagnostic unit for this purpose. 	Independent Operators JLR Retailers & Staff	The information for servicing on Jaguar vehicles can be downloaded from our online library called TOPIx: http://topix.landrover.ilrext.com/topix/vehicle/lookupForm The below is a screenshot of the website which shows the logins for:	nse	The resources invested in training by Jaguar Land Rover and its authorised service providers means that, whenever a Jaguar or Land Rover vehicle owner chooses to have their vehicle serviced at an authorised Jaguar Land Rover service centre, they know that they will receive, from an expert specifically trained in the servicing of Jaguar and Land Rover vehicles, a high quality service that meets Jaguar Land Rover's mandated standards.	because Jaguar Land Rover and its authorised repairers invest significant amounts of time and money into training, equipment and facilities, to ensure that authorised JLRA service providers can meet the high customer expectations and quality standards that are required of authorised Jaguar Land Rover service providers, as well as legislated safety standards.



VOLKSWAGEN

available via the following link: private customers with an electronic repair and workshop information service. Software for diagnostic tools is also Volkswagen AG provide a global web based solution that provides independent workshops, vehicle fleets and

	https://erwin.volkswagen.de/erwin/showHome.do
Assertion	Brand Response
VW Beetle 2003	
Brake bleed procedure it has air in the system (not just a normal flush) is specific to this model.	Procedure for brake bleeding is available in Erwin as is the software for diagnostic work.
Had to buy a factory manual from USA to get the	
scan tool. A function which our scan tool	
performed, nowever, we needed the procedure	
information to go with it. This car is 12 years old	
and the local dealership did not want to do the	
procedure and did not have the staff qualified to	
VW Golf	
An example; I was servicing a Volkswagen Golf.	A service book is provided with all Volkswagen vehicles where the service can be recorded, Software for
When I contacted Volkswagen to advise them we	diagnostic work to clear the service light is available via Erwin, there is also a manual override of the service light.
have serviced the vehicle and to please make a	This procedure is contained in the owner's manual supplied with the vehicle.
note of it and could you clear the service	
reminder I was told that it cannot be done as it	
was not serviced at Volkswagen and thus there is	
no way of logging the service, our solution for	
this was to purchase quite expensive equipment	
to clear this service reminder an expense adding	
service I think you would agree. The same	
request came from the customer, to a dealer,	
and was offered a flat refusal, (no proof of	
service or cost to clear the reminder was	
discussed). The customer said, they don't own	
my car how can they have that power?	
0 0 0 0 0 0	
VW Caddy	

One example. We had to replace the ignition barrel, cylinder & key on a VW Caddy, parts the dealer happily sold me, when it came time to commission the new ignition cylinder with our scan tool, the 4 digit code required was not accessible for me from the dealer. Four phone calls and the promise that the service department will get back to me never eventuated.

Vehicle immobilizer data is intentionally not made available, as this could potentially be used for the theft of motor vehicles. VGA treat this data with the utmost respect and confidentiality.

FORD	
Assertion	Brand Response
Ford Territory Ghia	
Steering angle sensor failure. Whole steering	The comments mention the sensor needs to be programed first and then calibrated. This is fals; the
column needs to be replaced. Once replaced the	steering angle sensor only requires to be calibrated to the straight ahead position. This can be achieved
steering angel sensor has to be programed to	with after-market tools similar to those from Bosch.
suit the vehicle. (Not just calibrated) it needs to	
be programed first after it's been replaced and	
then calibrated. We had to return the vehicle to	
do the dealer to have it programed. (They also	
calibrated it) We can calibrate, but cannot	
program it.	
Ford FG Falcon	
We had a FG falcon with an air bag issue from	The Dealer took 2 days to program the airbag module for the crash repair shop. Please see the dealer
the crash shop that our scan tool diagnosed a	
faulty air bag module. Sourced a new genuine	a number of vehicle configurations (e.g. with and without curtain bags, with and without seat bags). All
module from local Ford dealer and had to get it	these configurations use one of a couple of modules, so tailoring to the application is needed. This
programmed by local dealer. Car was mobile so	module configuration can be achieved with after-market tools similar to those from Bosch
we drove this to the dealer. They said could we	
leave it with them, they took 2 days and charged	
us excessively to programme vehicle, client not	
happy and we nearly lost contract with crash	

shop over delays even though we told them it	
vehicles in the city, not sure what you would do	
in the country to get them to a dealer?	
Ford Focus/Ford Mondeo/Ford Transit	
These vehicles require special tools to replace	Focus, Mondeo and Transit timing belt / chain replacement tools: these tools are for alignment of the
the timing belts/chains and cannot be purchased	camshafts, crank shaft and prior injection pumps. These tools can be fabricated easily or purchased
locally through the dealer network. We are	over the internet and or ordered from our tool supplier Bosch directly.
prepared to purchase the tools as a group – but	
they specifically stated that we cannot buy these	
network and have a lot of experience in the	
dealer network. Without the tools, it is	
impossible to undertake testing or replacement.	
2012 Ford Ranger	
With regard to companies not sharing/releasing bulletins on known faults, an example occurred	This was a campaign and can be easily found on google or by going to the Australian recall site.
on a 2012 Ford Ranger with 47000km were a coolant hose wore through on a fuel line, the	
local dealer made mention that they are looking	
the vehicle. Fixed price servicing is another issue	
and without going on and on, again I have	
examples of a not so level playing field.	

HOLDEN	
Assertion	Brand Response
Holden Astra TS	
We had a client with a TS Astra that had an	Access to program this vehicle is through the AC Delco TDS site (acdelcotds.com). Programming
engine ECU fault requiring a replacement ECU.	interface will be required e.g. MDI or Tech2

	VE Commodore
	though.
	scan) we were able to buy the parts from Holden
interface will be required e.g. MDI or Tech2	ECU, needs to go to Holden dealer (even with G-
Access to program this vehicle is through the AC Delco TDS site (acdelcotds.com). Programming	No reprogrammable procedure for replacement
	Holden Zafira
	vehicle at their shop to repair.
	accessible voltage pin outs. Holden dealer needs
Service information for this vehicle is available at GME Infotech (gme-infotech.com).	Steering position/angle sensor code, no
	XC Barina Z14xe
	from the dealer for a fee.
	for a PIN code which could only be obtained
	reinitialise vehicle with scan tool and was asked
	Holden Dealer. Fitted module and went to
	reversing sensors which was purchased from
This security code is supplied with the vehicle in the owner manual wallet.	Vehicle required a replacement module for
	VE Commodore
	control.
	vehicle damage whilst in tow truck operators'
	house to save inconvenience and possible
	download and unlock/programme vehicle in
	to us. Would have been happy to pay a fee to
	programming fee and tow truck the vehicle back
	truck the vehicle to a dealer in the city, pay a
	get our client back on the road we had to tow
	programme the ECU for 3 days "too busy" so to
	vehicle, our local dealer stated they could not
	dealer but it had to be programmed into the
Service information access location is gme-infotech.com.	We purchased a new genuine ECU from our local

Assess the control is through the AC Deleg TDS site (and length com)	
	VE Commodore
	communicate with this new computer, but without being "hooked into Holden's network" the part cannot be taught the programming.
	has the right to fit a new part. Scan tools can
	withheld the rights to say that only a dealership
	I then have to have the car towed hundreds of
	particular optioned model (auto climate control, ABS and so on).
	told/programmed it is being fitted to my
Service information access location is gine-inforecti	herause the computer has to be
	dealership) The local technician can source a
interface will be required e.g. MDI or Tech2	garage (I'm hundreds of kilometres from a
Access to program this vehicle is through the AC Delco TDS site (acdelcotds.com). Programming	Model breaks down, I have it towed to my local
	Astra 2004 AH
	to nearest dealer? Which could be 250km away
	Sometimes we have to say "sorry you need to go
	Sometimes you're lucky & can say to the
	out card" This is a hit and miss approach.
	play the "we get parts off you, could you help
	which we have recently spent money with and
	will usually target or ask the particular Dealer
	The others are a case of it's who you know. We
	opened) no retrievable data/specs.
	staving on (supposed to switch off after door is
Access to program this verificie is through the Ac Delco 103 site (accentotics.com).	body withig diagrams/voitage pill outs for door

externally the vehicle would have multiple repairs to alternators and ECU's. Without information channels open from manufacturers,	Programming interface will be required e.g. MDI or Tech2
updates to onboard software as issues became evident have to be returned to the dealership, most workshops own scan tools with the ability	
to bi-directionally communicate with vehicle	
electrical systems, and in the event of an update could be provided the software to correct	
factory issues with programming.	
700	
A 2001 Holden Rodeo came to our workshop.	Access to service, diagnostic information and programming for this vehicle is available through the AC
Vehicle won't start - check engine light on.	Delco TDS site, acdelcotds.com (SI under legacy publications section).
Carried out diagnostic procedure to determine	9
fault. Reconditioned fuel pump. Fitted new	Programming interface will be required e.g. MDI or Tech2
immobilizer and keys. Contacted local Holden	
Hiring a Tech and Holden's tech? computer to	
carry out interface with ECU. Dealer refused to	
help us in any way. (Dealer had sold this vehicle	
6 weeks earlier with check engine light on and	
told customer they fixed it). Several phone calls	
to ask again for help – refused. Contacted Metro	
Holden 75km away and they were happy to help.	
Sent vehicle to Adelaide at my own expensed	
task requested. Vehicle then sent back to us.	
Local dealer refused to help us and it was	
suggested by us to tow the vehicle to them for	
interface and they also refused this suggestion.	
We then asked if the customer could bring the	
יכוווכוכ מוזכבר גס נוזכווו מוזם נוזכץ מוסס וכומסכם נס	

Renault Megane II 2007 We are unable to reset the service due indicator. The manual procedure (Autotech/Autodata) doesn't work. G-scan doesn't have that special function. Unley Renault say the vehicle needs to go to them! I know the Renault is a bit obscure but we actually have it here today. Renault Megane II 2007 The 2007 Megane II does not require a scan tool to reset the service due indicator. It is reset using the vehicle's display reset button and the instructions on how to do this are included in the owner's manual (see attached). See attached). PhII NIJ 761-4 FING P	help them.	
ا ت ٥	RENAULT	
٦. ٥	Renault Megane II 2007	
0		The 2007 Megane II does not require a scan tool to reset the service due indicator. It is reset using the
<u> </u>	The manual procedure (Autotech/Autodata)	vehicle's display reset button and the instructions on how to do this are included in the owner's manu-
•	doesn't work. G-scan doesn't have that special	(see attached).
	function. Unley Renault say the vehicle needs to	*PDF
	go to them! I know the Renault is a bit obscure but we actually have it here today.	No. of the second secon
	טטר אב מרנומווץ וומעב ור ווכוב נטטמץ.	Pages from Meg II PhII NIJ761-4 FNG PI

Mercedes-Benz	
Assertion	Brand Response
Mercedes Sprinter	
Unable to purchase work shop manual or specific	We (at head office), have not received any requests for access to our repair data, which would indicate
wiring info from dealers in Adelaide. Ended up	very low demand, and in our view a single case study about a workshop manual does not indicate a
purchasing on line from states. Some of the	systemic issue or concern.
above concerns we eventually get around but for	 Access to the US or European Service & Parts Net system is unavailable in Australia, as it is only
example the Mercedes w/shop manual took 8	available to residents of the EU or US respectively.
days. I know I don't have to tell you that's 8 days	
of a customer calling (2 times a day) 8 day's a	
bay is blocked up.	
Mercedes A190	
We had a 2009 Mercedes A190 towed to the	We are currently in the process of updating our theft-relevant parts policy which will allow independent
workshop from another repairer. The Steering	repairers to purchase theft-relevant parts provided that they work with an authorised repairer to
lock was faulty and would not turn the steering	comply with the same identification and legitimisation requirements as authorised repairers, in order to
wheel or start. Mercedes once sold you the new	maintain the appropriate levels of vehicle security and public safety.
Steering lock and Green program key to program	
the steering lock into the vehicle. As of this year	

the vehicle to a Mercedes workshop and for them to fit and program the part. It will cost a minimum \$500 just to install the part and tow the vehicle before the cost of the part is added. Ignition Switches and keys come under this rule now too. This is costly for the client and time

\$280 incl GST Nissan X Trail Power windows must sometimes be reset to ensure the anti-pinch function operates. Resetting power windows is impossible without having the process to reset them, or the location of the hidden reset button. Safety then becomes an issue as children and adults with small fingers can experience severe pinch injuries.
\$280 incl GST Nissan X Trail Power windows must sometimes be reset to ensure the anti-pinch function operates. Resetting power windows is impossible with having the process to reset them, or the loc of the hidden reset button. Safety then becan issue as children and adults with small file can experience severe pinch injuries.
\$280 incl GST Nissan X Trail Nissan X Trail Power windows must sometimes be reset to ensure the anti-pinch function operates. Resetting power windows is impossible with having the process to reset them, or the loc of the hidden reset button. Safety then becan issue as children and adults with small file can experience severe pinch injuries.
\$280 incl GST Nissan X Trail Nissan X Trail Power windows must sometimes be reset to ensure the anti-pinch function operates. Resetting power windows is impossible with having the process to reset them, or the loc of the hidden reset button. Safety then bec
\$280 incl GST \$280 incl GST Nissan X Trail Power windows must sometimes be reset to ensure the anti-pinch function operates. Resetting power windows is impossible with having the process to reset them or the local power windows.
\$280 incl GST Standard design of the design
\$280 incl GST Sometimes he reset to power windows must sometime to be reset to power windows must sometime to be reset to power windows must sometime to be reset to power windows.
\$280 incl GST Standard dedict of the part
\$280 incl GST
\$280 incl GST
cilaiged Stiff on lift on allocated degree cit
charged \$110.00 incl CCT apothor dealer of
back to dealer for force burn. One dealer
dealer and after fitting new filter needed to go
Brought a diesel particulate filter from a Nissan
Nissan diesel
Assertion
NISSAN
consuming.
now too. This is costly for the client and time
Ignition Switches and keys come under this rule
the vehicle before the cost of the part is added.
minimum \$500 just to install the part and tow
them to fit and program the part. It will cost a
the vehicle to a Mercedes workshop and for
the green program key. They want you to tow
they will not sell you the steering lock or supply
or sull to troth to the

	this impacts the customer and our business.
	had to send the customer to the manufacturer
	so we were unable to complete the work and
	dealer but they wouldn't release the information
	vacuum reading which we requested from the
FCAI web site.	at our Erina store and needed the manufactures
This is the type of information that can be supplied if the repairer makes contact with Nissan via the	We were recently testing a Nissan Patrol Diesel
	Nissan Patrol Diesel
	dealer.
	have to pay another \$350 to take it back to the
	forked \$350 in a tow fee, he did not want to
	to their incompetency. Besides he had just
	was the last place he wanted to take his car due
	back to the dealer, he got upset, because this
	the customer was told his car would have to go
	therefore cannot initialise the module. When
	be he lacks access to Nissan software and
	cause. Anyhow Steve now has communication
	that any repair shop could miss such a basic
	This is really the very basics and it shocks me
	problem which happened to be a blown fuse.
	It did not take Steve very long to discover the
	Wiring issue.
	car to an auto electrician because he had a
	module and told the customer he had to take his
	module and could not communicate with the
	to be programed to the car. Nissan fitted the
	The same of the sa

ТОУОТА	
Assertion	Brand Response
Toyota dealer refused to give repairer a copy of	Toyota dealer refused to give repairer a copy of Toyota Australia provides detailed repair information to the aftermarket through our website
Automatic transmission wiring diagram so	www.toyotamanuals.com.au on a paid subscription model (available for \$5.42/day) and is not provided

repairer sent customer to Toyota Dealer to get fixed. Toyota reconditioned transmission at a cost of \$5000.00 and two weeks later fault returned. It was a faulty solenoid not found on first overhaul.

There are other instances of Dealers not releasing information and wanting vehicle back for repairs and special tools not available to aftermarket.

I know programming is a bit specialised but we have invested in training and equipment that gears us up to perform these tasks and are held back by lack of resources.

google organic search rankings. through our Dealer network. This website has been advertised extensively and currently ranks 3rd on

sources of repair information to the aftermarket The website can also be located through the FCAI website that summarises participating manufacturer's


Toyota Dealer (except the tool that contains vehicle security functions) Each repair manual contains the part numbers of Special Service Tools that can be ordered through any

Other instances should be detailed to enable a response.

Window motors need to be 'timed' v

Window motors need to be 'timed' when refitted. This information is not provided by the manufacturer or the dealer.

refer to the example below as extracted from the vehicle repair manual This information is available in the repair manual through our website at www.toyotamanuals.com.au



Toyota Data Subscription

We paid for access over a specific time period and basically gave up trying to download some material. Didn't have the right configuration so stuffed around and had no support we gave up. I have been having issues with accessing some of the manuals on the website, particularly the wiring diagrams.

It can be a little annoying when you pay for a subscription and cannot access the information that they advertise as having available.

The information is there, I believe, but the design of the website and the old manual format makes it impossible to access them. I have spoken to Toyota several times about this and their response is that they are not responsible for the material that is on the website and it is controlled by a third party.

The latest update by email from them yesterday is that we cannot use any computer other than Windows 7 or older 32 bit machine with Internet Explorer 8.0 installed. Now, I have no idea how they expect us to operate a secure computer system and run a web browser that was released in 2009 on our computers.

This is a ridiculous response in my opinion and indicative of the general attitude towards this half-assed attempt at sharing information.

So I would recommend that you be careful and do not purchase any more than a one day

occurred upgraded to accommodate Internet Explorer IE11 and we regret any inconvenience that may have compatibility issues that require significant development, however the website has recently been manuals that were developed well before the latest browser releases and this can result in some Toyota's repair manual website <u>www.toyotamanuals.com.au</u> contains a significant number of older

requires installation To access the electrical wiring diagrams a 3rd party program - Adobe SVG Viewer (free download)

All of the PC requirements as well as the software requirements to effectively view repair manuals are subscription in the final payments section contained in the "Systems Requirements" section and need to be acknowledged prior to agreeing to the

The website also has a customer support section available for assistance.

subscription.	
2011 Toyota Hiace	
Came from a Toyota that they fitted a new Air condition compressor the bill from Toyota was more than \$2500 but the air con still did not	The comment relates to diagnosis conducted on a vehicle with an unauthorised accessory fitted and does not relate to the availability of repair information to the aftermarket.
work so Toyota told the owner that it needed a new ECU and they had to programed in but they has no ECU in Australia and the car owner had to wait for more than 4 weeks for it to come. It	Toyota Australia does not offer a GPS tracker as an option or an accessory on its model line-up, please refer to the installer of this product.
wait for more than 4 weeks for it to come. It was one of Britz Australia vans that we do work for so was ask to have look.	
This car did not need a new ECU or the new AIR con compressor in fact it did not need any parts to the get the air con to work??	
This car had GPS tracker fitted to the can low can high wires had communication interference so lout the GPS system and rewired it and the AIR con work again	
I did ph the Toyota and ask then why did they put a new AIR con compressor and why did they order a new ECU when it was GPS communication interference? But they did not want to say anything?	
Britz Australia did not need to take this car to Toyota but they are the only ones that can Programme a new ECU that it did not need.	

2012 Toyota Prado

This is a 80,000km logbook service which includes the diff and transfer oils to be replaced. When I look up Valvoline or Castrol for the right oil specification, I am told dealer only oil.


When I call up my Toyota dealer I am told that they do not sell this oil, they only have it in bulk and the car will need to go to their service department.

I have spent a good part of the day working out what oil to use, and it turns out that it is unlikely the dealer is actually using the correct recommended dealer oil, as I have discovered this particular dealer buys their oil in bulk from Castrol and Castrol do not sell the dealer specified oil for this car. So the plot thickens. I see this as a deception not only to the public but also to the aftermarket repairer, it is also very restrictive on the consumer's choice of repairer.

Also since upgrading the software on a few of my aftermarket scan tools, I have lost the level of ability that I use to have with my Toyota platform. It is like I have a very basic level and I can no longer carryout the diagnostic tests and reading that I had before my update. (I actually had this happen to 2 of my many aftermarket scan tools that have). There has been a fairly recent court case with a well-known Chinese scan tool manufacturer Maxisys who has been sued by some manufacturers for reveres

This information is available in the following locations:

- Owner's manual contains detailed information on the oil specifications required for the vehicle.
- In the specified repair manual that can be sourced from www.toyotamanuals.com as per below sample.



ယ္ Where local oil suppliers decide to not make available oils that are required for our vehicles, Toyota makes these oils available for sale through our Toyota Dealer Parts departments

this may have sent shock waves throughout the Aftermarket scan tool manufactures and this		
may be the reason for the downgrade we are		
now seeing.		

Isuzu Truck	
Assertion	Brand Response
Isuzu uses factory codes that differ from generic	This example relates to Isuzu trucks and is not covered by the existing Agreement, the FCAI or Isuzu
OBD2 compliant codes, resulting in diagnostic	Utes Australia.
Technical information from Isuzu is not available	
in Australia and Isuzu's overseas website uses	
different diagnostic codes.	
In the end I now know the code I had P0122	
converts to the factory code P02E8 and this code	
points to the IAF position sensor, once I knew	
this, my job only took one hour to fix, had I know	
dono and directed in one have been proceed their interest of the second procedure of the second procedure in the second proced	
took 6 hours including the time spent in research	
and accessing the US Isuzu technical web site.	
Had I had the correct info on this fault code the	
job would have only taken 1 to 1.5 hrs but	
without this info it has taken 6 hours.	
2009 Isuzu NPR 200	
I am sure this is no surprise but Isuzu trucks will	This example relates to Isuzu trucks and is not covered by the existing Agreement, the FCAI or Isuzu
not sell me or for that matter Autodata technical	
information needed for the repair and	
diagnostics on a 2009 Isuzu NPR 200 small truck.	
I have accessed the US Isuzu paid site and	

Compared the second Sec	is different to our Australian mode. Autodata,	is different to our Australian mode. Autodata, VACC to which I have access through my MTAQ membership all have the same story – Isuzu Australia refuse to sell them technical data	
	0 TO	IINTOTTUNATEIV THE WITHE BILIE TO THE ENGINE ECO	
is different to our Australian mode. Autodata,		VACC to which I have access through my MTAQ	
is different to our Australian mode. Autodata, VACC to which I have access through my MTAQ	VACC to which I have access through my MTAQ	membership all have the same story – Isuzu	
is different to our Australian mode. Autodata, VACC to which I have access through my MTAQ membership all have the same story – Isuzu	VACC to which I have access through my MTAQ membership all have the same story — Isuzu	Australia refuse to sell them technical data	

a repair information portal for overseas models, their account was suspended. Even with access Volvo advised an independent repairer to access to the UK site, information does not cover Australian address, the independent repairer subscription. As it is not possible to choose and to which the independent repairer already had a Assertion Australian variations. had registered as a UK user and consequently

would fit us in when they could) and cost an programmed by the dealers only. We had to restuffing around we were told it need to be A customer brought in their Volvo in that had the dealer who kept her car for 2 days (as they book the customer in and drive her vehicle to work. Finally after multiple phone calls and hours of non billable time trying to get it to needed to be programmed in and we wasted neglected to let us know that the ABS module it for the customer however the manufacturers part directly from the manufacturer and installed Lock Braking system). We purchased the correct revealed that it needed a new ABS module (Anti the ABS light on dash, after some diagnosis it

Brand Response

ONTO

Case 1

We anticipate a response to our enquiry within weeks. weeks that the process to gain access to the site has changed and we are currently seeking clarification information is referred to the Volvo Cars international web site. We have become aware over recent We acknowledge the issue as reported and advise that the Volvo process is for all requests for technical from our parent company as to the revised process and access rights for countries outside of the EU

equipment there is little if any difference in price between franchised dealers and independent that when repairs are undertaken using the manufacturer defined processes and with the necessary vehicles. The allegation that the vehicle owner "felt it necessary to resume using the dealer" confirms of knowledge independent repairers have with the technology present in all many contemporary any obligation to inform the purchaser of the repair process, and this matter is evidence as to the lack repairers. franchised dealer, although the report is not specific in this regard. I don't believe VCA or the Dealer has the ABS module from "the manufacturer" in this instance. Presumably it was purchased from a All parts sold by VCA are via the franchised Dealer network and as such the repairer did not purchase

an the by but the but additional \$300+ which we could not charge out to our customer and also had to provide the customer with a loan vehicle. The customer was

extremely inconvenienced without a car for days	
and we were out of pocket around \$500.00 for	
the job as we tried to keep the customer happy	
by keeping the price as close as possible to our	
estimate, but in the customers eyes she felt that	
it is necessary to resume using the dealerships	
because she feels that we don't have the	
equipment to repair her vehicle properly. This is	
just one example we endure from vehicle	
manufacturers every single day. This costs my	
business and exponential amount of money each	
year and seriously hinders our ability to offer a	
fair and competitive service in my trade.	
BMW	
Assertion	Brand Response
BMW 520D 2012 Diesel Auto	
BMW manufacturer are not providing there	The BMW Group has a customer facing web portal called "OSS" or the Online Service System for BMW
customers or us with the vital information as to	Service, MINI Service, BMW Motorrad Service and Rolls-Royce Motor Cars Service.
where to find a simple engine number.	
I have been asked for a quote on a 68,000 klms	The OSS portal provides non BMW workshop with access to the repair and service information.
recommended service schedule	Login page: https://oss.bmw.de
	I have gone into OSS and located, downloaded and attached a copy of the relevant information showing the engine number locations for the vehicle as defined in the enquiry – BMW 520d 2012 Diesel Auto.
	The engine in this vehicle is called an N47, which is shown in the attached document.
	The information is located in our platform called the "Integrated Service Technical Application" or "ISTA

any special tools or programs) and carries out the service according to information provided by the required, the servicing workshop reviews data which is stored in the vehicle (which is accessible without distance based program, it looks at the actual vehicle usage. In order to define what service items are means that the vehicle only has the work carried out that is actually required, it is not just a time or schedule, we use a program called "Condition Based Servicing", using the BMW CBS servicing program As for the service schedule, for some 15 years or so, BMW vehicles do not have a standard service

Servicing requirements Also attached are two pages from the 5 Series owners handbook which describe the Condition Based



location OSS ISTA.pd







Maintenance P281.pdf

either purchase or manufacture hard copy log books for the customer to keep for services no of logging the service, our solution for this is to serviced at Land Rover and thus there is no way service schedule) and to please make a note of it vehicle (according to the factory recommended Rover to advise them we have serviced the Rover on their database, when I contacted Land rather the service must be logged with Land These vehicles do not have a hard copy log book, 2013 Land Rover Discovery 3.0 Ltr Turbo Diesel I was told that it cannot be done as it was not

Brand Response

LAND ROVER

is therefore not a system that independent repairers who are not JLRA franchisees can access. authorised JLRA dealers as a condition of those dealers' membership of the JLRA franchise network and The Online Service History (OSH) system forms part of the IT system that JLRA makes available to all

benefit and convenience of the customer, all services performed on a vehicle by a JLRA-authorised staff and the vehicle owners themselves service centre in a secure database which is readily accessible to both JLRA-authorised service centre The OSH system is designed to enable JLRA-authorised service centres to electronically record, for the

improving upon) the manual service logbook system that preceded it, the OSH system is designed to By recording only services performed by JLRA-authorised service centres, consistent with (but

longer done by the dealer, a sub-par and unnecessary expense adding service. The log book should be controlled by the car owner and not the dealership – if the owner would like us to register that the service was completed by qualified staff, using fit for purpose parts and according to the specification, then this is what should occur.

give prospective second-hand vehicle purchasers confidence in the quality of the services recorded in the online logbook for a given Jaguar or Land Rover vehicle.

JLRA-authorised dealers or service centres doing so It is open to Jaguar and Land Rover vehicle owners to have their vehicles serviced at any repairer or JLRA does not impose any restrictions on vehicle owners' choice of repairer and is not aware of any service centre of their choice, including independent repairers who are not JLRA-authorised repairers

to sell their vehicle in the future. receipts and invoices as records of those services for prospective purchasers to inspect should they wish independent repairer to record those services in their own vehicle logbook and/or retain copies of It is open to Jaguar and Land Rover vehicle owners who choose to have their vehicles serviced at an

conducted by a JLRA-authorised service centre. should the owner need to provide an independent repairer with any details of previous services It is also open to vehicle owners to access their own vehicle's records on the OSH system at any time

It is similarly open to independent repairers themselves to innovate and offer competing electronic record-keeping systems in response to consumer demand for such add-on benefits.

See attached

}

JLRA Response to

correspondence - 26 SACCC re Access to On

Suzuki Vitara has an issue with the ESP light Suzuki Vitara coming on. The owner has been to severa Assertion **Brand Response** This matter relates to Technical Service Bulletins, which are outside of the scope of the Industry Agreement.

a result of any small voltage fluctuations. He has unit that causes the ABS and ESP to shut down as dealer network of a known fault within the ABS diagnosis. Wow. Both dealerships technicians sparky. The dealers both came to the same module and addressed it with an upgraded revised ABS module. I think that it is criminal been quoted \$3,500.00 for the repair with a There was a document released within the they must be very well trained! No, not really. came to the exact same diagnostic conclusion, workshops, two Suzuki dealers and an auto known manufacturing fault. customer still has to pay for the repair of a module but even when it is a design flaw the that Suzuki have discovered a flaw in the control

Suzuki Vitara 2008

We recently had a 2008 Suzuki Grand Vitara that has an issue with EGR Valve, we purchased the part from local dealership and then was told that after the fact that it needed a connector set, then to have to try and get technical information that was not forthcoming from that dealership. Contacted another dealership through Repco connections and they sent to us information that should have been originally supplied with parts. The vehicle went to local dealership eventually leaving us with footing the cost for their diagnostic recording when they could have informed us originally the procedure for this vehicle. This has left us greatly out of pocket as owner paid dealership and not us.

This is something that should not have occurred.

always welcome to contact us via our customer service portal with their request, and in the past we times in the past. have always provided them with the necessary information they are seeking, which we have done many we don't have a dedicated portal due to the small volume sales of our vehicles our customers are As far as Suzuki Australia are concerned regarding access to Service and Repair Information, although

AUDI	
Assertion	Brand Response
Audi Q5 2011	Audi Australia and AUDI AG have made all the service/body repair information available to independent repairers via the FCAI website. The independent repairer will be charged a flatrate in order to view the Online Service Information via erWin Audi. The independent repairer can acquire these via the main navigation item "Flatrate". There are different flatrate scales available to suit their requirements: 1 hour with printing rights (screenshot only) (€7.00), 1 day with printing rights (€30.00), 7 days with printing rights (€130.00), 30 days with printing rights (€310.00) or 365 days with printing rights (€2850.00). The independent repairer can view all "Online service information" from erWin Audi during the time span they selected and, depending on their flatrate charge, also print it out. When this time is up, the independent repairer will not be under any obligation to select anything.
	http://www.fcai.com.au/service-repair/member-service-repair
	https://erwin.audi.com/erwin/showHomeAssistant.do
We needed to drain and refill engine oil as an Audi q5 2011 with a CGLB engine. Audi don't	The information about the engine oil for an Audi Q5 2011 can be found within erWin and the vehicle is equipped with an electronic oil gauge available from the multi media display within the vehicle. This has
give out the fill quantity and there is no dipstick. The owner's manual says take it to Audi	been designed so the owner can check the oil level without lifting the bonnet.
Audi A4 Petrol	
A recent example was servicing a 2014 Audi A4 Petrol, we completed the service items as per	With regards to the Audi A4 2014, Audi Australia don't use long life service as described and the service indicator can be reset by following the repair information available from Erwin. Most repairers have
the service schedule and ticked these items off	access to either a generic scan tool or vagcom which allows them to reset the service indicator.
as being serviced in the service book. These	
vehicles have a Long Life Service reset that no generic scan tool can reset. The vehicle was	
returned to Audi to reset the Long Life Service	
and Audi refused to rest the Long Life Service	
Reset because they did not do the service. The	

Service reset but the Dealer still refused.	customer offered to pay to have the Long Life	

KIA	
Assertion	Brand Response
Kia Cerato 2006	
Ok the OEM's are blocking us from security	We have investigated the example provided on September 27 th and wish to advise our findings r
codes and pins, but surely the customer has the	to the matter raised by the AAAA relating to the supply of security codes and pins.
legal right to this info. I suggest your proposed	
code should reflect that sensitive information	l asked our Queensland District Service and Parts Manager to investigate the concerns raised with
that we the repair cannot access should be made	Dealership and he was unable to determine who specifically handled the query from the repaire
available to our customers on their request and	customer.
proof of ownership of their car.	

relating

usual scan tool process of handshaking the ECU Needing to replace a faulty ECU I began with the then found a 6 digit pin being required. to the body control and immobilizer system.

contacted Eagers Kia for assistance on retrieving would never hand that over to an independent the code I was informed that by "law" that they place for the code had been left blank. I then workshop. I went to the owner's booklet and found the

passed the information over to the owners of then have to show proof of purchase and show I was then told that the only way they can give the vehicle identification before this would be allowed. I that code was to the owner. The owner would

> rer or vith the

have taken reasonable steps to ensure the security of the data random VIN or registration numbers to obtain vehicle immobilizer security codes and to ensure that we released to the owner. This method is used to ensure that individuals are not able to simply supply processes to ensure that proof of ownership is verified by one of our dealers and the codes would be in relation to the contact made with our office, the advice provided to the customer was in line with our

cover administration of our dealers and at the dealers discretion a small fee may be charged for providing this information to We agree that the registered owner has the right to obtain the required code for their vehicle from one

should be handled. codes, we will shortly issue a notification to our Dealer network to again emphasize how such enquiries To ensure clarification on the subject of handling procedures for the issue of security or immobilizer

They rang the workshop, of which the story then changed. They were told that the vehicle would have to come to them, they would enter the code (at a cost to the customer of course) themselves and not let the owner know what the code was.

I suggested that they contact the place of purchase and try a more subtle approach. I told them to say they needed a key replaced and that they required the pin. They were given a Sydney number to call, of which they kindly told the owners, all you need to do is drive to the dealer, prove you're the owner and show ID and that number should be handed over.

Seems like a different set of rules from dealer to dealer. I believe if you purchase the vehicle, then all information of the vehicle is yours as well. Shows that this battle is far from over.

This only allows the dealer to have an unfair advantage of equally equipped workshop like ours. We are have to have a criminal check and pay a license fee to access this information which is rightfully the customers anyway.