Subject: FW: ACCC - New car retailing industry market study - further information requests [SEC=UNCLASSIFIED] 1A - Snap-On Scan Tool.PNG; 1B - Scan Tool - VW POLO - Live Data - System Attachments: Voltage.jpg; 1C Erwin EU - Repain Manuals.JPG; 1D - Nissan-Idle Relearn.pdf; 1E - Scan Tool - Mitsubishi Pajero - DTCs.JPG; 1H - Mitsubishi Techinfo.PNG; 1F - Mitsubishi Australia - Contact Us.PNG; 1G - NCR - Further data request - website and repair information - KTAS Updat....docx From: Thomas Hatch Sent: Tuesday, 28 March 2017 4:48 PM To: Adam Pay < Adam. Pay@kmart.com.au > Subject: ACCC - New car retailing industry market study - further information requests [SEC=UNCLASSIFIED] Response to information requested Wednesday, 22nd March: Every KTAS store is equipped with a Snap-On 'Modis Ultra' or 'Solus Ultra' diagnostic scan tool. These tools provide the user with access to the on-board diagnostic (OBD-II/EODB) and electronic operating systems on a modern vehicle (now essential for most fault finding and repair processes). Snap-On Diagnostic web page http://www.snapontools.com.au/diagnostics/diagnostics_platforms/modis_ultra_ - Jpeg of scan tools

Pic of diagnostic tool showing the alternator voltage problem in the 2012 model Volkswagen Polo attached
 (1B)

attached (1A)

- o In regards to the screenshots of the AU Erwin site versus the EU or US Erwin site about the voltage problem, I'm actually unaware of an AU Erwin site. The FCAI member service info/repair link also directs you to the euro site.
- I have attached a screenshot of the EU site (1C)
 <u>https://erwin.volkswagen.de/erwin/showSearchArticle.do</u>

 Note I often run into difficulty at payment screen when making a purchase from Aus. Also, some manuals are only supplied on CD (via post).

- The Mitsubishi EU site https://www.mitsubishitechinfo.eu/ (1H) showing what information is available versus the Australian site https://www.mitsubishi-motors.com.au/about-us/contact-us (1F)
 - Scan tool showing faults with 2014 Mitsubishi Pajero (1E)
- Below are the Nissan repair/service sites regarding the idle recalibration procedure when the battery is removed, along with the information obtained otherwise from the internet
 - o (1D) Info obtained from the internet http://prostream.com.au/wp-content/uploads/2015/04/Nissan-IAVL1.pdf (unsure if Nissan would be too pleased about this doc)
 - o http://www.nissan-techinfo.com/Home.aspx (EU site) Note very limited content available for online viewing (mainly supplied via CD or hard copy)
 - o http://www.nissan.com.au/Owners/Owners (AU site)
 - o techdata@nissan.com.au (email address supplied on the FCAI members repair info page)
- Below are the five (5) examples (as requested) of types of new cars where replacing or reconnecting a battery causes the car to no longer function properly, along with an outline what the effect of doing so would be on the car and what would need to be done to fix it
 - The vast majority of modern vehicles require some form of re-initialisation or re-learn process following a standard battery change, with the most common known as battery registration (a process which allows a vehicles management system to monitor and manage operating systems accurately following a battery change). The impact in most cases if a new battery is not registered the on-board computer will bring on a warning light and limit operating functions (as a safeguard), restricting drivability. Left unresolved, the battery and/or charging system could be damaged.
 - o The following makes and models all require battery registration of some type:

- Make	- Model	- Year
- Volkswagen	- Golf - 1.2 TSI	- 08/12-on
	Petrol FWD	
	Hatchback	
- BMW Mini	- MINI - One D	- 07/10-on
	Diesel FWD	
	Hatchback	
- Peugeot	- 308 - 1.6 16V	- 02/08on
	Petrol FWD	
	Wagon	
- Land Rover	- Discovery - 3.0	- 09/09on
	TD 4x4	
- Audi	- A3 – 1.4 TFSI	- 04/12-on
	Petrol FWD	

- Many more examples available (if required)
- o Note that most new car warranties do not cover the battery (normally limited to 12 months).
- In regards to time and other costs gather the information needed, whether that information is available from the manufacturer's website or a data aggregator, or if it needs to be obtained from another source? We find most data aggregators don't list this type of information. We are however, fortunate enough to have battery and equipment suppliers who are very active in closing information gaps in this space. The direct costs for this are hard to define from our perspective, but the resources they commit to obtain and compile the info would ultimately add to what we (and our customers) pay for their products.


Regards,

Tom Hatch National Equipment, Maintenance & Quality Manager

Store Support Office / The Barwell Centre, Level 2, 7-9 Barwell Ave, Castle Hill NSW 2154 T (02) 9680 6584 / F (02) 9680 8170 / M 0439 604 197/ W ktas.com.au







Sud pone

Other er Win Shops: er Win AUDI AG er Win SEAT er Win SKOI

About erWin Products and services Vehicle-specific information Individual vehicle information My erWin

If the information icon it is Last searched VIN: Logged in as thatch an overview. None Info MKB/GKB Polo (2010 - 2015) Polo A05 [6R,6R1,6C1] Individual vehicle information Training items > Repair information Model-specific repair information Repair manuals Return to product assistant Title Contents Type key" Search results Back to search Search path Info medium Model(s)

This lists all of the search results in the icon.

displayed, you can view the table of contents of the document by clicking To view a document you must have a valid flat rate.

CYZ8...

CEMA

CHZB...

> 3-cylinder direct-injection engine (1.01 engine, 41/ EA 211, turbocharger)

SG1 BAS.

oga

601

000

681

003

681

ogs

▶ 3-cylinder injection engine (1.0 Lengine, 4 V, EA 211)

▶ 3-cylinder injection engine (1.21 engine, 21/ EA 111)

3-cylinder injection engine (1.21 engine, 41/ EA 111)

3-cylinder common rail engine (1.41, 4V, turbocharger, EA 288)

3-cylinder common rail engine (1.21, EA189)

REPAIR MANUALS

681

ogs

139

op

CHYA...

Settings

Surface	English	Article	English

CGPA

CHER

CPTA

COZC

4-cyl, direct injection (1.2 l, 4V, EA 211, turbocharger)

14-cyl. direct injection (1.41, 41/, EA 211, turbocharger)

621 6CI...

ogs

563

oga

681

ops

601

ogs

DA3A...

+cyl. direct injection engine (1.81, 4 V, EA 888 Gen III, turbocharger, chain drive)

4-cyl. direct injection engine (2.0 | 4/ turbocharger, toothed bet drive)

♣ 4-cyl. injection engine (toothed belt drive)

9N1 SN3

90

> 4-cyl. hjection engine with timing chain

681

oga

Attachment 1C

-
8
A
111
10
-
2
5
· O
roll
5
mmo
con
linder
1
-
-1
8
1
m
H

CAYC...

CLSA

BUD...

CDCD







Technical Bulletin: Idle Air Volume Relearn Procedure.

Models affected:

Nissan X-Trail T30 Nissan Tiida





Background:

With progressive carbon build up around the throttle valve and throttle bore area, the engine control unit will adapt to these long term changes by adjusting the base idle speed, base injector pulse width and ignition timing.


When the throttle body is cleaned, or the battery is removed these vehicles "May" require an idle air volume relearn.

Symptom: After a Prostream intake service has been completed, the engine "May" have a tendency to idle erratically from 1500 -2000 rpm.

Cause: The engine control unit is unsure of the current throttle valve position and air mass quantity after carbon removal. The control unit must be put through an "Idle Air Volume Relearn" procedure with a dedicated scan tool. Please read this procedure in FULL prior to carrying out!

Procedure:

- Connect the Snap On scan tool to the 16 pin OBD 2 connector located at the lower dash trim drivers side.
- 2. Check and clear any current engine fault codes (codes only)
- 3. Select correct vehicle in vehicle selection (model, year etc.)
- 4. Select engine section.
- 5. Select "Special functions" (or Work Support mode on other scan tools).





6. Select "Self Learning Cont.", click on start, this will reset engine control units Adaptives to "0"




7. Select *Idle Air Volume Relearn* "make sure you follow the prerequisites listed on the screen before you begin, engine temperature between 50-80 C, transmission temperature, no loads, transmission in P/N, A/C, idle speed at 650 rpm, ignition timing etc. You can check these on the data list.





Make sure all of the *Prerequisites* are met, Tip: you can check this in live data first.





9. Please Note!


Before you begin the idle air volume relearn (IAVL) procedure, shut the engine **off**, loosen the clamp for the plastic induction tube at the throttle body end.

Start and run the engine, slowly remove the induction tubing to bleed in unmetered air into the engine.

This procedure will allow the engine to idle low enough to perform the (IAVL), if the engine is idling higher than 650 rpm or hunting the relearn will not work! Once the rpm has stabilized, press continue on the scan tool to perform the IAVL


While doing this try to maintain idle speed to 650 rpm or below, prevent the engine from stalling (you may need a staff member to assist).

Press Continue:





10. Start the IAVL relearn by pressing Continue





11. If successful the screen will display **Complete:** The engine should now idle at the specified idle speed (700 ± 50 rpm) the process is now complete. It is not uncommon to require several attempts for this procedure to work.





13. Refit the induction tube.

12. Shut the engine off.

- 14. **Start** and run the engine, the engine should now idle to specification.
- 15. Check for any *diagnostic trouble codes* and record, clear any code's.
- 16. **Road test** the vehicle, make sure A/C is turned on, run vehicle through all gears, drive through complete drive cycle, up hill, down hill, idle, around corners etc. make sure malfunction indicator lamp does not illuminate during road test.
- 17. Reconnect scan tool, **recheck for diagnostic trouble codes**, confirm system pass, make sure intake tubing and air box is secure, vehicle is ready for customer hand over.

MODIS LIELS

2014 Mitsubishi Pajero NW 3.2L-DT L4

P0102

P0113

Intake Air Temperature Sensor High - Active DTC

Mass Air Flow Sensor Low - Active DTC

Code List

MITSUBISHI ENQUIRIES

If you have a enquiry about Mitsubishi please enter your details in the form below and hit the 'submit' button. Your query will be forwarded to our customer service team who will respond to your email. We wish to help you get your query resolved so please provide all of the correct mandatory information to allow us to respond as quickly as possible.

We also have some helpful information on our website on the links below which may help assist:

- General Frequently Asked Questions
- Accessories
- Outlander PHEV
- Vehicle Maintenance
- Diamond Advantage Warranty
- Capped Priced Servicing
- Roadside Assistance

© CUSTOMER ASSISTANCE

1300 13 12 1

If you have a questix comment about Mits any of our vehicles p call us.

Type of enquiry":	(Please Select)
/ehicle*;	(Please Select)
Title1:	(Please Select)
irst Name";	
Last Name':	
Telephone type:	Mobile Home Phone
	Business
Nobile Number':	
Email Address*:	
Postcode1:	
Dealership Name":	
MIN'S	
Registration Number*:	
Comments (optional):	

Table 1: Links to Australia's top 10 car manufacturers' (2016)¹ Australian, EU and US repair and service websites and subscription cost webpages

Manufacturer	Manufacturer repair/service website and subscription page (EU)	Manufacturer repair/service website and subscription page (US)	Manufacturer repair/service website and subscription page (AU)	Notes
Toyota	https://www.toyota- tech.eu/Menu/Repair	http://techinfo.toyota.c	https://toyotamanuals.c om.au/	
Mazda	https://mapps.mazdaeur .com/mud/registerio.ht ml#44DACAD6-8F60- 47EB-89CA- 686FE8DEFFEB	http://www.mazdaservic einfo.com/	https://mazdamanuals.c om.au/	
Hyundai	https://www.hyundaitec hinfo.com/	http://service.hyundai- motor.com/	No Portal (email only): technical@hyundai.co m.au	
Holden	https://www.gme- infotech.com/	https://www.acdelcotds. com/acdelco/action/tec hinfo	https://www.acdelcotds. com/acdelco/action/ho me	
Ford	http://www.etis.ford.co m/home/charging.do	https://www.motorcraft service.com/Home/Prici ng/7	https://www.motorcraft service.com/Home/Prici ng/7	Site provides good illustration of data restrictions in AU. Switch country/region to view (select 'pricing information' for further detail).
Mitsubishi	https://www.mitsubishit echinfo.eu/Subscription. aspx	https://mitsubishitechinf o.com/epacarb/	http://i- car.com.au/technical- information/ https://www.fcai.com.a u/service- repair/member-service-	No Portal Available (links only to FCAI & I- CAR OEM info pages to
Nissan	http://www.nissan- techinfo.com/find.aspx? dept_id=10	https://login.eu.nissan.b iz/nidp/idff/sso?id=NissB 2B&sid=0&option=crede ntial&sid=0⌖=http s://eu.nissan.biz/#	No Portal (email only): techdata@nissan.com.a u	show gap) EU must call for pricing info (& obtain e-token)
Volkswagen	https://erwin.volkswage n.de/erwin/showHome. do	https://erwin.vw.com/er win/showOrderFlatrate. do	No AU portal	(FCAI provide link to EU portal - site will not accept payment from AU IP)
Subaru	https://techinfo.subaru. com/index.html	https://techinfo.subaru. com/index.html	AU - no content available online - Data available via CD only (see CD order form link in notes)	https://www.subaru.co m.au/service/service- and-repair-manuals

_

¹ http://www.drive.com.au/motor-news/toyota-hilux-is-australias-bestselling-vehcile-20170104-gtm6jz.html

Honda				
	https://techinfo.honda.c om/rjanisis/logon.asp	https://techinfo.honda.c om/rjanisis/logon.asp	AU - no content available	EU & US shared site


Table 2: Screenshots from car manufacturer's Australian, EU and US repair and service websites for popular models from each of Australia's top 5 car manufacturers' (2013–2016) about the types of oil (specifically: crankcase, transmission, differential and power steering) required to service the car


Manufacturer/ Model (specify year 2013–16)	Manufacturer repair/service website (EU)	Manufacturer repair/service website (US)	Manufacturer repair/service website (AU)
Toyota Corolla	1A.	1B*	1C.1D
Mazda Mazda3	2A. 2B*	2C*	2D. 2E. 2F.
Hyundai i30	3A.	3B*	N/A
Holden Commodore	4A*	4B.	4C.
Ford Ranger	5A*	5B	5C.

^{*}Registration/Account verification restricted

Toyota Corolla EU -

1A.







Toyota Corolla US – cannot provide information (account locked)

Toyota Corolla AU -

1C.




1D.



Note - glitch with AU site. 2013 Corolla selected, however Rav 4 information is provided?

Mazda 3 EU -



Mazda 3 US -

2C.



SITE USAGE AGREEMENT | CONTACT US | PRIVACY

THIS SITE IS OPTIMIZED AND CERTIFIED FOR MICROSOFT INTERNET EXPLORER 7.0 OR GREATER, WE DO NOT RECOMMEND OR SUPPORT OTHER INTERNET BROWSERS.


THIS SITE AND ITS CONTENTS ARE INTENTED FOR THE CONTINENTAL U.S. AND CANADA ONLY. FOR OTHER MARKETS, PLEASE GO TO www.mazda.com.

PRIVACY/CA PRIVACY @2017 MAZDA NORTH AMERICAN OPERATIONS. ALL RIGHTS RESERVED

Mazda 3 AU -

2D.





e. Driving in mountainous conditions continually

mainly where none of the following conditions apply.

*5: SKYACTIV-G and SKYACTIV-D vehicles can select flexible setting only some countries in Europe. Consult an Authorized Mazda Repairer for details. Flexible setting can be set if the vehicle is operated.


OIL FILTER REPLACEMENT [SKYACTIV-G 1.5, SKYACTIV-G 2.0, SKYACTIV-G 2.5]

id0111h8800700


Warning

- Hot engines and engine oil can cause severe burns. Turn off the engine and wait until it and the engine oil have cooled.
 A vehicle that is lifted but not securely supported on safety stands is dangerous. It can slip or fall, causing death or serious injury. Never work around or under a lifted vehicle if it is not securely supported on safety stands.
 Continuous exposure to USED engine oil has caused skin cancer in laboratory mice. Protect your skin by washing with
- soap and water immediately after working with engine oil.

- . If engine oil is spilled on the exhaust system, wipe it off completely. If you fail to wipe the spilled engine oil, it will produce fumes because of the heat.
- 1. Remove the service hole cover (installed to front under cover No.2) used to remove the oil filter.



2. Remove the oil filter using the commercially available, cup-type oil filter wrench (67 mm {2.6 in} diameter, 14 sided).



- 3. Use a clean rag to wipe off the mounting surface.
- 4. Apply clean engine oil to the O-ring of a new oil filter.
- 5. Tighten the oil filter according to the instructions on the package or side of the oil filter.


Tightening torque (reference value)

12-16 N·m {123-163 kgf·cm, 107-141 in·lbf}

- 6. Start the engine and confirm that there is no oil leakage.
 - · If there is oil leakage, repair or replace the applicable part.
- 7. Inspect the oil level. (See ENGINE OIL LEVEL INSPECTION [SKYACTIV-G 1.5, SKYACTIV-G 2.0, SKYACTIV-G 2.5].)
- 8. Install the service hole cover.


Hyundai i30 EU -

3A.




Note - i30 Marketed as Elantra in EU

3B.



GM (Holden) EU

4A.




GM (Holden) US - (not sold in US. Cadilac CTS used for purpose of exercise) – 4B.



Note - Cadillac CTS used for demonstration purposes

Holden Commodore AU -

4C.



Ford Ranger EU -


5A.



FordService is not available for your selected Market (Australia).


Ford Ranger US -

5B.



Ford Ranger AU -

5C.







- Workshop Manual
- Training Material
- · Owner's Manual
- Service Bulletins

Newsletters

ECU Reprogramming

· On-Board Diagnostics

- PDI and Periodic Maintenance
- Open Diagnostics Exchange
- Parts Catalogue
- * Special Tools

Jser Name

Password

Submit

Click here to become a new member Forgot User ID? or Password?



MITSUBISHI MOTORS EUROPE B.V.

vehicle identification, service handbooks, technical manuals, component and diagnosis information, wiring type, information provided concerning, and delivered by means of, proprietary tools and equipment, data diagrams, diagnostic trouble codes, the software calibration identification number applicable to a vehicle record information, two-directional monitoring, test data as well as Workshop Manual information and Welcome to the Vehicle Repair and Maintenance Information website of Mitsubishi Motors Europe On this website you can retrieve the following information as of MY11 Mitsubishi vehicles Training Material.

The services provided on this website will only be provided to professional users and not to consumers.

Before using the information Mitsubishi Motors strongly advises, and recommends you to carefully read the Warning & Cautions mentioned in the information

substribing to this site. For models you cannot retrieve the information you require, please contact your You must check which Mitsubishi model(s) are available through this site before registering on and/or local Mitsubishi Motors Authorized Service Point Before you will use the information from this website ensure yourself that you are technically competent to use the information correctly



Mitsubishi Motors North A... +



Last Updated Document

25-12-16 Newsletter- ENL10-018

