

Good morning,

Please find below an additional example that was received last night. I do hope this can be included in our submission.

Thanking you in advance.

Ultra Tune Fyshwick – ACT

Vehicle Volvo C70 2.5L Turbo Coupe Auto 2008, delivered by tow truck, no start condition.

Found quickly battery had one bad cell. Replaced battery.

Still no start (no crank either). Bypass electronics and actuate starter motor, engine spinning but not firing, no spark, no fuel.

Suspect immobilizer issue. With no electrical schematics available, outsourced job to an auto-electrician (mobile) who faced the same issue and could not do anything, and then to a second auto-electrician (workshop), no schematics either. Car sent to dealership today.



Tania Plumpton

National Customer Service Manager

Unit 15, 762 Toorak Rd, Glen Iris VIC 3146

PO Box 2086, Camberwell West VIC 3124

Phone: +61 3 9815 9200 | **Mobile:** 0400 051 694 | **Fax:** +61 3 9815 9201

taniap@team.ultratune.com.au |

www.ultratune.com.au |    

Please consider the environment before printing this e-mail.

This email is intended for the use of the individual or entity named above and may contain information that is confidential and privileged. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this email is strictly prohibited. If you have received this email in error, please notify us immediately by return email or telephone +613 9815 9200 and destroy the original message. Thank you.