

Mandatory Injury Report Details

Product Safety Number PS1099074

Report Details

Report number	PS1099074
Web Reference Number	accs-psa-mr:64058
Date submitted	09/03/2022
Consent to disclose	Yes

Primary Contact Details

Anonymous	False
Title	
First name	
Last name	
Business Phone	
Home Phone	
Mobile Phone	
Email address	KmartACCCMandatoryReporting@kmart.com.au
Address line 1	690 Springvale Road
Address line 2	
Address line 3	
City/suburb	Mulgrave
State	VIC
Postcode	3170
Country	Australia

Supplier Responsible for this product

Supplier Type

<input type="radio"/>	Importer	<input type="radio"/>	Distributor	<input type="radio"/>	Exporter	<input type="radio"/>	Wholesaler
<input type="radio"/>	Manufacturer	<input type="radio"/>	Service Provider	<input checked="" type="radio"/>	Retailer	<input type="radio"/>	Other Supplier

Supplier name	Kmart Australia Ltd.
ABN	
Supplier phone	
Supplier phone 2	
Supplier email	
Supplier website	
Supplier address 1	
Supplier address 2	
Supplier address 3	
Supplier suburb	
Supplier state	
Supplier postcode	
Supplier country	
Business Organisation	

Product

Name	Sneaker comfort slip on mesh
Brand	
Description	casual shoe
Product Category	
Country of manufacture	China
Country of origin	China
Recommended retail price	
Approx lifespan of product	
Product is subject to a recall	No
PRA Number	

Released under FOI

Demographics										
Product intended age ranges(s)					Where was the product supplied?					
<input type="radio"/>	Baby	<input type="radio"/>	Toddler	<input checked="" type="radio"/>	Nationally	<input type="radio"/>	Qld	<input type="radio"/>	NSW	
<input type="radio"/>	Child	<input checked="" type="radio"/>	Teen	<input type="radio"/>	Vic	<input type="radio"/>	Tas	<input type="radio"/>	ACT	
<input checked="" type="radio"/>	Adult	<input checked="" type="radio"/>	Senior	<input type="radio"/>	NT	<input checked="" type="radio"/>	Online	<input type="radio"/>	WA	
<input type="radio"/>	Older Australian			<input type="radio"/>	SA	<input checked="" type="radio"/>	International	<input type="radio"/>	Not Known at this time	
Countries where the product was exported										
Country name					Country code					
New Zealand					NZ					
Identifying Number										
Has identifying numbers					Unknown					
Other identifying number										
Best before date										
Use by date										
Dates product was supplied										
Date from					Date to					
Stock quantities supplied										
Total quantity supplied										
Imported into Australia										
Exported from Australia										
Manufactured in Australia										
Traders who sold the product										
Describe What Happened										
<p>The customer claims once the grip wears out, the sole becomes slippery and smooth on the bottom. The customer advised [REDACTED] had been wearing the shoes every day since September, walking in them for about 1hr each day On this day as the customer stepped down a step, with [REDACTED] right foot, the right leg slipped from under [REDACTED] resulting to damage to the tibia fibula and ankle</p>										
Incident Type										
<input type="radio"/>	Death			<input checked="" type="radio"/>	Serious injury			<input type="radio"/>	Serious illness	
				1						
Incident Details										
Type of incident					Serious Injury					
Date incident occurred					11/01/2022 11:00 AM					
Date made aware of the incident					08/03/2022 11:00 AM					
Incident Location					[REDACTED]					
Date and time food or drink was consumed (if applicable)										
Date or time of onset of symptoms (if applicable)										
Description of illness, symptoms or injuries					Severe break requiring surgery					
Name of the injured					[REDACTED]					
Gender					[REDACTED]					
Age group										
Permission to disclose the details of the affected person					Yes					
Phone number					[REDACTED]					
Email address										
Known injuries					Severe break requiring surgery					
Business where the product was purchased or consumed										
What action(s) have you taken or intend to take in relation to the product or service										
the customer's sample will be sent in to head office for investigation.										
Attachment(s)										
Attachment Name		Attachment Type			iManage No		iManage Processing Status			

Released under FOI

